

Final Reclamation and Stormwater Inspection

December 21, 2018

Operator: ANADARKO E&P ONSHORE LLC - 2800

Location ID: 380608

Inspection Document #: 674902364

Cheyenne County, CO

NESW Section 21 T14S R46W

Russell Beam
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: ANADARKO E&P ONSHORE LLC - 2800/14S46W21

Location ID: 380608



Photo 1. Photo taken from the location, facing North. Appears the Operator has performed final reclamation activities. However, several locations throughout the site lack uniform perennial vegetation and are covered in weedy, annual vegetation which includes but not limited to kochia.



Photo 2. Photo taken from the location, facing South. See comments from Photo 1.

Inspection Photos

Location Name: ANADARKO E&P ONSHORE LLC - 2800/14S46W21

Location ID: 380608



Photo 3. Photo taken from the location, facing East. See comments from Photo 1.



Photo 4. Photo taken from the location, facing East. See comments from Photo 1 and note the debris left on site.

Inspection Photos

Location Name: ANADARKO E&P ONSHORE LLC - 2800/14S46W21

Location ID: 380608



Photo 5. Photo taken from the reference location , facing North. Note the uniform perennial grass cover.



Photo 6. Photo taken from the reference location , facing East. See comments from Photo 5.

Inspection Photos

Location Name: ANADARKO E&P ONSHORE LLC - 2800/14S46W21

Location ID: 380608



Photo 7. Photo taken from the reference location , facing South. See comments from Photo 5.



Photo 8. Photo taken from the reference location , facing West. See comments from Photo 5.