

Final Reclamation and Stormwater Inspection

December 21, 2018

Operator: VECTA OIL & GAS LTD – 10267

Location ID: 418793

Inspection Document #: 674902360

Cheyenne County, CO

SWSW Section 12 T14S R47W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: VECTA OIL & GAS LTD – 10267/14S47W12

Location ID: 418793



Photo 1. Photo taken from the location, facing East. Appears the Operator has performed final reclamation activities, with the evidence of drilling rows and straw crimped mulch. However, the majority of the site is barren or covered in weedy, annual vegetation which includes but not limited to field bindweed and kochia, with little perennial grass cover establishment.



Photo 2. Photo taken from the facility, facing North. See comments from Photo 1.

Inspection Photos

Location Name: VECTA OIL & GAS LTD – 10267/14S47W12

Location ID: 418793



Photo 3. Photo taken from the facility, facing West. See comments from Photo 1.



Photo 4. Photo taken from the facility, facing West. See comments from Photo 1.

Inspection Photos

Location Name: VECTA OIL & GAS LTD – 10267/14S47W12

Location ID: 418793



Photo 5. Photo taken from the reference location , facing North. Note the uniform perennial grass cover.



Photo 6. Photo taken from the reference location , facing East. See comments from Photo 5.

Inspection Photos

Location Name: VECTA OIL & GAS LTD – 10267/14S47W12

Location ID: 418793



Photo 7. Photo taken from the reference location , facing South. See comments from Photo 5.



Photo 8. Photo taken from the reference location , facing West. See comments from Photo 5.