

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/26/2018

Submitted Date:

12/27/2018

Document Number:

682600590**FIELD INSPECTION FORM**
 Loc ID 321567 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 70430Name of Operator: PINTAIL PETROLEUM LTDAddress: 225 N. MARKET #300City: WICHITA State: KS Zip: 67202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Houseburg, Karen	316-263-2243 off/74165	khouseberg@pintailpetroleum.com	316-263-6479 fax
Atterbury, Mike		Mike.Atterbury@darrahoil.com	All Inspections
Walter Innes Phillips		pintail@pintailpetroleum.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
150335	UIC DISPOSAL	AC	09/10/1992		-	CHAMPLINN 205 AMOCO A-1	EI
207313	WELL	IJ	02/01/2017	DSPW	017-06248	CHAMPLIN 205 AMOCO A 1	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

This location is in the process of being transferred to Darrah Oil Company. Darrah informed of stained soil issues via phone call 12/26/2018.

Multiple pipeline risers on location with no lock out tag out (LOTO) tag in violation of COGCC Rule 1105. See corrective action.

Unused equipment stored on location.

Stained soil near truck loadout and inside tank berm. See attached photos. Location was wet from stormwater at the time of inspection. No free fluids other than stormwater observed at the time of inspection.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment stored on location. See attached photos		
Corrective Action:	Comply with Rule 603.f .		Date: 01/28/2019
Type	STORAGE OF SUPL		
Comment:	Barrel of unmarked fluid stored on location. Barrel appears to contain crude oil. Container is open allowing wildlife access. See attached photos.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff.		Date: 12/29/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	Tank	>= 5 bbls		
Comment:	Stained soil in northwest corner of tank battery. See attached photos.			
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.			Date: 01/28/2019
Crude Oil	Truck Loadout	<= 1 bbl		
Comment:	Stained soil at truck loadout. See attached photos.			
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.			Date: 01/28/2019

In Containment: No

Comment:

☒ Multiple Spills and Releases?**Equipment:**

Type: Flow Line	# 2		corrective date
Comment:	Disconnected flowline risers near treater and wellhead not LOTO. See attached photos.		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.		Date: 01/28/2019

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 150335 Type: UIC API Number: - Status: AC Insp. Status: EIFacility ID: 207313 Type: WELL API Number: 017-06248 Status: IJ Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600591	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4687956