

# Inspection Photos

API: 05-071-06362

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 12/21/2017

## Inspection Photos



**Photo 1.** Facing south toward the location. Only one well appears at the location.

## Inspection Photos



**Photo 2.** The west side of the location appears to have been disturbed and does not have adequate vegetation cover.

## Inspection Photos



**Photo 3.** Facing southeast toward the cut slope. There is sparse vegetation and the soils are susceptible to erosion.

## Inspection Photos



**Photo 4.** Facing southeast toward the cut slope.