

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/27/2018

Submitted Date:

12/27/2018

Document Number:

689302781**FIELD INSPECTION FORM**

Loc ID 335130 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211539	WELL	PR	05/29/2002	GW	045-07299	WESTER/HEATH RMV 237-28	PR
282384	WELL	PR	09/14/2006	GW	045-11762	VASSER/HEALTH RWF 543-28	PR
282385	WELL	PR	09/14/2006	GW	045-11761	VASSER/HEALTH RWF 443-28	PR
286757	WELL	PR	09/15/2006	GW	045-12747	VASSER/HEATH RWF-444-28	PR

**General Comment:**[Routine Field Inspection.](#)[ANY CORRECTIVE ACTION \(S\) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE.](#)

### Location

<b>Lease Road:</b>			
Type	Access		
comment:	Snow covered.		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Tank sign unlegible.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	01/27/2019

Emergency Contact Number:

Comment: 1-970-285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused piping on location.		
Corrective Action:	Comply with rule 603.f	Date:	03/27/2019
Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panel fence.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panel fence.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panel fence.		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date
Type: Horizontal Heated Separator	# 4			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	500 gallon methanol tank at separators.			
Corrective Action:				Date:
Type: Plunger Lift	# 4			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 3			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 2			
Comment:				
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:	2 tanks in centralized battery.				
Corrective Action:					
				Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211539	Type:	WELL	API Number:	045-07299	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	282384	Type:	WELL	API Number:	045-11762	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	282385	Type:	WELL	API Number:	045-11761	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	286757	Type:	WELL	API Number:	045-12747	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302782	Inspection photo 689302782	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4688557">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4688557</a>