

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/28/2018

Submitted Date:

12/28/2018

Document Number:

689302807**FIELD INSPECTION FORM**Loc ID 335444 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		COGCC.inspections@caerus oilandgas.com	all Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278812	WELL	PR	11/03/2005	GW	045-10941	GMU 23-8C (H23NW)	PR
278813	WELL	PR	11/07/2005	GW	045-10940	GMU 23-2C (H23NW)	PR

General Comment:Routine Field Inspection.
Location is snow covered.

Location

Lease Road:			
Type	Access		
comment:	Snow covered.		
Corrective Action		Date:	

Overall Good: ☒

Emergency Contact Number:			
Comment:	1-800-791-7691		
Corrective Action:		Date:	

Good Housekeeping:			
Type	OTHER		
Comment:	Stained rock in battery containment, see photo.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.		Date: 01/28/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:					corrective date
Type: Bird Protectors	# 2				
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:					Date:
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:					Date:
Type: Vertical Heated Separator	# 2				
Comment:					
Corrective Action:					Date:
Type: Pig Station	# 1				
Comment:					
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	HEATED STEEL AST		,
Comment:					

Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected FacilitiesFacility ID: 278812 Type: WELL API Number: 045-10941 Status: PR Insp. Status: PR**Producing Well**Comment: Well Producing on plunger lift.

Corrective Action:

Date:

Facility ID: 278813 Type: WELL API Number: 045-10940 Status: PR Insp. Status: PR**Producing Well**Comment: Well Producing on plunger lift.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Compaction				

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302808	Inspection photo 689302808	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4689478