

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/28/2018

Submitted Date:

12/28/2018

Document Number:

689302819

**FIELD INSPECTION FORM**

Loc ID 334954 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		COGCC.inspections@caerusoilandgas.com	<a href="#">all Piceance inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265382	WELL	PR	03/21/2003	GW	045-09004	BENZEL 35-8B (H35B)	PR
265384	WELL	PR	03/11/2003	GW	045-09007	BENZEL 35-1C (H35B)	PR
265387	WELL	PR	11/20/2002	GW	045-09005	BENZEL 36-4C (H35B)	PR

**General Comment:**

[Routine Field Inspection.](#)  
[Location is snow covered.](#)

**Location**

**Lease Road:**

Type	Access				
comment:	Snow covered.				
Corrective Action	L			Date:	

Overall Good:

Emergency Contact Number:

Comment:	1-800-791-7691			Date:	
Corrective Action:				Date:	

**Good Housekeeping:**

Type	TRASH				
Comment:					
Corrective Action:				Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#		corrective date
Vertical Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 265382 Type: WELL API Number: 045-09004 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Well Producing on plunger lift.](#)

Corrective Action:

Date:

Facility ID: 265384 Type: WELL API Number: 045-09007 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Well Producing on plunger lift.](#)

Corrective Action:

Date:

Facility ID: 265387 Type: WELL API Number: 045-09005 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Well Producing on plunger lift.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302820	Inspection photo 689302820	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4689484">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4689484</a>