

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/02/2019

Submitted Date:

01/02/2019

Document Number:

689302864

FIELD INSPECTION FORM

Loc ID 334829 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Elsener,		COGCC.inspections@caerusoilandgas.com	all Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211177	WELL	PR	12/30/1994	GW	045-06936	BENZEL 36-16	PR
266184	WELL	PR	06/11/2004	GW	045-09116	BJM 31-13A (P36)	PR
266185	WELL	PR	02/20/2004	GW	045-09117	BENZEL 36-15A (P36)	PR
269296	WELL	PR	01/22/2005	GW	045-09347	BENZEL 36-9C (P36)	PR
269298	WELL	PR	02/25/2008	GW	045-09346	BJM 31-13D (P36)	PR
269595	WELL	PR	02/14/2004	GW	045-09385	BENZEL 36-15A1 (P36)	PR

General Comment:

[Routine Field Inspection.](#)

Location

Lease Road:			
Type	Access		
comment:	Road is snow covered and not plowed.		
Corrective Action			Date:

Overall Good:

Emergency Contact Number:			
Comment:	1-800-791-7691		
Corrective Action:			Date:

Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLs	STEEL AST		,
Comment:	<input style="width: 100%;" type="text"/>				

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST			
Comment: 2 tanks in a centralized battery.						
Corrective Action:					Date:	

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>211177</u>	Type:	<u>WELL</u>	API Number:	<u>045-06936</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:				Date:					
Facility ID:	<u>266184</u>	Type:	<u>WELL</u>	API Number:	<u>045-09116</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:				Date:					
Facility ID:	<u>266185</u>	Type:	<u>WELL</u>	API Number:	<u>045-09117</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:				Date:					
Facility ID:	<u>269296</u>	Type:	<u>WELL</u>	API Number:	<u>045-09347</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:				Date:					
Facility ID:	<u>269298</u>	Type:	<u>WELL</u>	API Number:	<u>045-09346</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:				Date:					
Facility ID:	<u>269595</u>	Type:	<u>WELL</u>	API Number:	<u>045-09385</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302865	Inspection photo 689302865	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4692509