

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401890534

Date Received:

01/02/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed

0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Howard Aamold

9703045014

howard.aamold@nbleenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 679300053

Inspection Date: 12/10/2018

FIR Submit Date: 12/11/2018

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 318333

Location Name: EDWARD HEMPLE UNIT-64N65W Number: 20NWNW County: _____

Qtrqtr: NWN Sec: 20 Twp: 4N Range: 65W Meridian: 6
W

Latitude: 40.302270 Longitude: -104.692220

FACILITY - API Number: 05-123- -00 Facility ID: 318333

Facility Name: EDWARD HEMPLE UNIT-64N65W Number: 20NWNW

Qtrqtr: NWN Sec: 20 Twp: 4N Range: 65W Meridian: 6
W

Latitude: 40.302270 Longitude: -104.692220

CORRECTIVE ACTIONS:

1 CA# 120930

Corrective Action: On the next Form 19 subsequent operator is to provide the root cause of the incident and preventative measures that will be taken to prevent reoccurrence on this and other dump lines at this location. Please give the location of the failure (i.e. 6 O'clock position) and if the root cause is corrosion explain if it is external or internal. Please also list the wells associated with this facility on the Form 19 subsequent.

Date: 03/05/2019

Response: CA COMPLETED

Date of Completion: 01/02/2019

Operator
Comment:

Damaged flow line observed in excavation at the time of inspection was an abandoned flow line left by previous operator.

Flow line in operation (shut in), that runs through excavation appears to be not damaged and will be pressure tested before excavation is closed.

COGCC Decision: _____

COGCC
Representative:

--

OPERATOR COMMENT AND SUBMITTAL

Comment:

--

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Howard Aamold

Signed: _____

Title: Environmental Coordinator

Date: 1/2/2019 2:33:14 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

--	--

Total Attach: 0 Files