

Inspection Photos

Operator: Logos Operating

API: 05-067-05524

Date: 12/19/2018



Photo 1. View of the project area from the western edge facing southwestward.



Photo 2. View of an erosional channel approximately 3 feet wide and 1 foot deep within the mid-western portion of the project area, downstream from the well.



Photo 3. View of the southern project area from the southwestern corner facing eastward. Vegetation is grazed and not in identifiable condition.



Photo 4. View of another erosional channel approximately 2 feet wide and 1 foot deep within the southwestern project area.