

Inspection Photos

Operator: BP America

API: 05-067-07595

Date: 12/19/2018



Photo 1. View of the northwestern project area from the well pad entrance facing eastward.



Photo 2. View the western project area from the northwestern corner facing southward.




Photo 3. View of musk thistle rosettes within the northern project area. Musk thistle debris was observed throughout the revegetation area.



Photo 4. View of an erosional channel approximately 1.5 feet wide and 10 inches deep within the northeastern project area.



Photo 5. View of the eastern project area from the northeastern corner facing southward. Vegetation is grazed and largely comprised of weedy annuals.



Photo 6. View of metal debris within the northeastern project area.