

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/26/2018

Submitted Date:

01/03/2019

Document Number:

682600596

FIELD INSPECTION FORM

Loc ID 321587 Inspector Name: Kosola, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 70430
Name of Operator: PINTAIL PETROLEUM LTD
Address: 225 N. MARKET #300
City: WICHITA State: KS Zip: 67202

Findings:

- 8 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Atterbury, Mike	316-202-4956	Mike.Atterbury@darrahoil.com	All Inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		pintail@pintailpetroleum.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207359	WELL	PR	03/03/1981	OW	017-06294	LOWE 4	EI

General Comment:

[This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.](#)

Location

Overall Good:

Emergency Contact Number: _____

Comment: _____

Corrective Action: _____ Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Above ground barrel containing crude is open to wildlife access. Netting on open tanks inadequate. Wildlife protections devices not adequate.		
Corrective Action:	Install or repair wildlife protection equipment or remove open barrel.		Date: 01/13/2019
Type	OTHER		
Comment:	Heater treater appears to be inoperable. Vessel should be repaired or removed if not intended to be used. Vessel is open allowing wildlife access.		
Corrective Action:	Install wildlife screen per Rule 605.b.(7).		Date: 02/04/2019

Overall Good:

Spills:			
Type	Area	Volume	
Crude Oil	Pump Jack	<= 1 bbl	
Comment:	Stained soil around pump jack. See attached photos.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 02/04/2019
Crude Oil	Tank	<= 1 bbl	
Comment:	Stained soil around tank. See attached photos.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 02/04/2019

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	# 4		
Comment:	Improper abandonment of flowline or crude oil transfer line (not purged, depressurized, risers cut 3' below grade, ends sealed, equipment removed) per 1105. Disconnected flowline risers not LOTO. Form 44 notice of abandonment not filed within 30 days. Local gov't designee and UNCC not contacted.		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.		Date: 02/04/2019

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL			STEEL AST		
Comment:	Tank appear to have leaked in the past or may currently have a leak. No leaking fluid was observed at the time of the inspection.				

Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	02/04/2019
--------------------	---	-------	------------

Paint

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 207359 Type: WELL API Number: 017-06294 Status: PR Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600599	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4693726