

# Construction and Storm Water Inspection

December 28, 2018

Operator: NOBLE ENERGY INC – 100322

Location ID: 458904

Inspection Document #: 674902382

Weld County, CO

SWSW Section 21 T3N R64W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W21

Location ID: 458904



**Photo 1.** Photo taken from the southern perimeter of the location, facing East. Photo illustrates a filterxx BMP that has been installed around the perimeter of the location.



**Photo 2.** Photo taken from the southeastern perimeter of the location, facing West. See comments from Photo 1.



## Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W21

Location ID: 458904



**Photo 3.** Photo taken from the southeastern perimeter of the location, facing North. Photo depicts breaks in the perimeter of the filtrex BMP .



**Photo 4.** Photo taken from the Eastern perimeter of the location, facing North. Photo depicts breaks in the perimeter of the filtrex BMP adjacent to open fenced pothole.



## Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W21

Location ID: 458904



**Photo 5.** Photo taken from the Eastern perimeter of the location, facing North. See comments from Photo 4.



**Photo 6.** Photo taken from the Eastern perimeter of the location, adjacent to the fenced pothole. The unfenced hole appeared to be greater than 3 feet depth.



## Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W21

Location ID: 458904



**Photo 7.** Photo taken from the northeastern perimeter of the location, facing West. See comments under Photos 3.



**Photo 8.** Photo taken from the northeastern perimeter of the location, facing South. See comments under Photos 3.

## Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W21

Location ID: 458904



**Photo 9.** Photo taken from the northwestern perimeter of the location, facing East. See comments under Photos 3.



**Photo 10.** Photo taken from the northeastern perimeter of the location, facing South.



## Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W21

Location ID: 458904



**Photo 11.** Photo taken from the Western perimeter of the location, facing South. Photo depicts soil placed over Filtrexx BMPs.



**Photo 12.** Photo taken from the Western perimeter of the location, facing South. Photo depicts soil Filtrexx BMPs apparently ran over by equipment.

## Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N64W21

Location ID: 458904



**Photo 13.** Photo taken from the southwestern perimeter of the location, facing East. See comments from Photo 1.



**Photo 14.** Photo taken from the southwestern perimeter of the location, facing North. See comments from Photo 1.