

# Inspection Photos

Operator: Hilcorp Energy

API: 05-067-08111

Date: 12/19/2018



**Photo 1. View of the southern project area from the southwestern corner facing eastward.**





**Photo 2. View the western project area from the southwestern corner facing northward.**





**Photo 3. View of northern project area from the northwestern corner facing eastward.**





**Photo 4. View of musk thistles (*Carduus nutans*) within the interim reclamation area.**





**Photo 5. View of kochia debris up to 4 feet tall at the entrance to the well pad.**