

Inspection Photos

Operator: Hilcorp Energy

API: 05-067-08106

Date: 12/19/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View the southern project area from the southwestern corner facing eastward. Revegetation is progressing, although grazed.



Photo 3. View of western project area from the southwestern corner facing northward.