

Inspection Photos

Operator: Enervest Operating

API: 05-067-05614

Date: 12/19/2018



Photo 1. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing within the interim reclamation areas.