



**Location**

Overall Good:

|                      |                 |  |       |
|----------------------|-----------------|--|-------|
| <b>Signs/Marker:</b> |                 |  |       |
| Type                 | WELLHEAD        |  |       |
| Comment:             |                 |  |       |
| Corrective Action:   |                 |  | Date: |
| Type                 | DRILLING/RECOMP |  |       |
| Comment:             |                 |  |       |
| Corrective Action:   |                 |  | Date: |

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                    |          |  |       |
|--------------------|----------|--|-------|
| <b>Fencing/:</b>   |          |  |       |
| Type               | WELLHEAD |  |       |
| Comment:           | Panel    |  |       |
| Corrective Action: |          |  | Date: |

|                    |     |  |                 |
|--------------------|-----|--|-----------------|
| <b>Equipment:</b>  |     |  | corrective date |
| Type: Plunger Lift | # 1 |  |                 |
| Comment:           |     |  |                 |
| Corrective Action: |     |  | Date:           |

|                    |  |  |       |
|--------------------|--|--|-------|
| <b>Venting:</b>    |  |  |       |
| Yes/No             |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

|                    |  |  |       |
|--------------------|--|--|-------|
| <b>Flaring:</b>    |  |  |       |
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Inspected Facilities**

Facility ID: 246039 Type: WELL API Number: 123-13836 Status: PR Insp. Status: WK

**BradenHead**

Comment: Bradenhead valve is exposed at surface.

Corrective Action:

Date: \_\_\_\_\_

**Workover**

Comment: Ranger Energy Services rig #22 is currently POOH with tbg for hydrotesting.

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Seeding          | Pass            | Seeding                 | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 674301391    | Photo       | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4695113">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4695113</a> |