

Inspection Photos

Operator: BP America

API: 05-067-09727

Date: 12/21/2018



Photo 1. View of the project area from the northwestern corner facing center. Plow is stored in the northwestern corner of the working area.



Photo 2. View the western project area from the northwestern corner facing southward.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of erosional rilling within the eastern project area.



Photo 5. View of kochia and Russian thistle debris along the eastern fenceline. Needs removal.