

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/19/2018

Submitted Date:

01/07/2019

Document Number:

679400278**FIELD INSPECTION FORM**Loc ID 318526 Inspector Name: CHESSON, BOB On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Silver, Randy		randy.silver@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Evans, Jacob		jacob.evans@nblenergy.com	
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241494	WELL	SI	10/01/2018	OW	123-09283	CHAMPLIN 525 AMOCO "A" 1	SI

General Comment:

Pump jack, emission control east of wellhead; pipeline riser, etc.to south; horiz treater and meter shed east of wellhead (out of service); 1 100 BBL FG PW tank (partially buried); 1 400 bbl oil tank (all production equipment out of service). Well and TB location is shut-in. No issues observed. See photos.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Other	
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241494 Type: WELL API Number: 123-09283 Status: SI Insp. Status: SI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679400279	Pump Jack and sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4696395
679400280	Wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4696396
679400281	Emission control and tank battery location (looking east)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4696397
679400282	Pipeline riser complex (looking south from pump jac)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4696398
679400283	Horiz. separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4696399
679400284	PW tank - tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4696400
679400285	Separator and meter shed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4696401
679400286	Oil tank - tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4696402