

Inspection Photos
Location Name: UPRR Kalcevic #22-3
Location ID: 320190



Photo 1 WH



Photo 2 TNK BTRY Signs on tanks not current operator

Inspection Photos
Location Name: UPRR Kalcevic #22-3
Location ID: 320190



Photo 3 leaking VLV and stained soil crude oil tank #75110



Photo 4 Stained soil 2" line next to separator

Inspection Photos
Location Name: UPRR Kalcevic #22-3
Location ID: 320190



Photo 5 Loc pic



Photo 6 not bird netting on sep stack

Inspection Photos
Location Name: UPRR Kalcevic #22-3
Location ID: 320190



Photo 7 unmarked riser by ECD



Photo 8 unmarked riser between sep and meter house