

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/07/2019

Submitted Date:

01/07/2019

Document Number:

688400987**FIELD INSPECTION FORM**Loc ID 320190 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|----------------|----------------------------|------------------------|
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| Gomez, Jason | | jason.gomez@state.co.us | |
| Powell, Harold | (918)-774-3120 | hpowell@petrosharecorp.com | Field Ops Manager |
| Brown, Devin | (303)-349-0302 | dbrown@petrosharecorp.com | Production Ops Manager |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 202957 | WELL | SI | 06/01/2018 | OW | 001-08362 | (UPRR) KALCEVIC 22-3 | SI |

General Comment:

Location

Overall Good: ☒

| | | | |
|----------------------|--|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | "Sign not legible Sign not updated to reflect current operator" | | |
| Corrective Action: | Install sign to comply with Rule 210.e. | Date: | 02/07/2019 |

Emergency Contact Number:

Comment: 303-500-1160

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Abandoned or unused lines by ECD and between sep and meter run. Need to mark and LOTO or remove per COGCC rules. | | |
| Corrective Action: | Comply with rule 1103 | Date: | 02/07/2019 |
| Type | OTHER | | |
| Comment: | Load line vlv on tank #75110 leaking at time of inspection. | | |
| Corrective Action: | Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. | Date: | 01/08/2019 |
| Type | OTHER | | |
| Comment: | Stained soil under load line vlv of tank #75110 and around 2" line next to separator. | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Bird netting missing on heated Separator stacks | | |
| Corrective Action: | Install wildlife screen per Rule 605.b.(7). | Date: | 02/07/2019 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|------------------|--|--|--|
| Fencing/: | | | |
| Type | | | |
| Comment: | | | |

| | | | |
|-----------------------------------|-----|-----------------|--|
| Corrective Action: | | Date: | |
| Equipment: | | corrective date | |
| Type: Horizontal Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | OTHER | Open Top | | , |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | 140BBL |
| Other (Type) | |

Berms

| | | | | | |
|---|----------|---------------------|---------------------|-------------|----------------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: Shares containment crude oil tanks | | | | | |
| Corrective Action: | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 4 | 300 BBLs | STEEL AST | 75113 | 39.907072,104.425354 |

| | | |
|--------------------|--|-------|
| Comment: | | |
| Corrective Action: | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 202957 Type: WELL API Number: 001-08362 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

BradenHeadComment: Plumbed to surface

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|---|---------|------------|
| At time of inspection found leaking VLV on load out lint to crude oil tank. Called emergency # spoke to operator he told me he would send some out immediately. | silverr | 01/07/2019 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 688400988 | loc pic | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4696524 |