

Inspection Photos

Operator: BP America

API: 05-067-08834

Date: 12/21/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View the eastern project area from the northeastern corner facing southward.



Photo 3. View of the northern project area from the northeastern project area facing westward.



Photo 4. View of what appears to be surface owner equipment within the southeastern project area.



Photos 5/6. View of noxious weeds, musk thistle (*Carduus nutans*) and jointed goatgrass (*Acroptilon repens*) within the interim reclamation area.