

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/07/2019

Submitted Date:

01/07/2019

Document Number:

679702494**FIELD INSPECTION FORM**

Loc ID 316496 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 6720Name of Operator: ROBERT L BAYLESS PRODUCER LLCAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|---------------------------------|
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us | |
| Waldron, Emily | | emily.waldron@state.co.us | |
| Trujillo, Helen | | notices@rlbayless.com | All inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 282581 | WELL | PR | 07/29/2006 | GW | 103-10671 | WEAVER RIDGE 27-1 | PR |

General Comment:[routine well inspection](#)

Location

Overall Good: ☒

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Sign or label not posted or information inaccurate on tanks or containers Tank volume capacity missing on labels. | | |
| Corrective Action: | Install sign to comply with Rule 210.d. | Date: | 03/11/2019 |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | Sign or label not posted or information inaccurate on tanks or containers. Black container at pump jack without label. | | |
| Corrective Action: | Install sign to comply with Rule 210.d. | Date: | 03/11/2019 |

Emergency Contact Number:

Comment: 505-327-0880

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused white container next to pump jack. | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 04/08/2019 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|---------------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 2 | | |
| Comment: | One container of methanol and 1 container of unknown fluid. | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |

| | | | |
|-----------------------------------|-----|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | 300 BBLs | STEEL AST | | 39.937730,-109.047710 | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| | | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CRUDE OIL | 2 | 300 BBLs | STEEL AST | | 39.937730,-109.047710 | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 282581 | Type: | WELL | API Number: | 103-10671 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | pump jack producing at time of inspection | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | | Compaction | | | | |
| Berms | | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 679702495 | inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4696683 |