

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401896339

Date Received:

01/08/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 56680

Name of Operator: MERRION OIL & GAS CORP

Address: 610 REILLY AVENUE

City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Waldron, Emily</u>		<u>emily.waldron@state.co.us</u>
<u>Kellerby, Shaun</u>	<u>970-712-1248</u>	<u>shaun.kellerby@state.co.us</u>
<u>Thompson, Philana</u>	<u>(505) 486-1171</u>	<u>pthompson@merrion.bz</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 679701950

Inspection Date: 11/30/2018

FIR Submit Date: 11/30/2018

FIR Status: _____

Inspected Operator Information:

Company Name: MERRION OIL & GAS CORP

Company Number: 56680

Address: 610 REILLY AVENUE

City: FARMINGTON State: NM Zip: 87401

LOCATION - Location ID: 316123

Location Name: BAXTER PASS-64S103W Number: 21NESE County: RIO BLANCO

Qtrqtr: NESE Sec: 21 Twp: 4S Range: 103W Meridian: 6

Latitude: 39.694710 Longitude: -108.955140

FACILITY - API Number: 05-103-00 Facility ID: 232180

Facility Name: BAXTER PASS Number: 43-21

Qtrqtr: NESE Sec: 21 Twp: 4S Range: 103W Meridian: 6

Latitude: 39.694710 Longitude: -108.955140

CORRECTIVE ACTIONS:

1 CA# 120738

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 12/31/2018

Response: CA COMPLETED

Date of Completion: 12/29/2018

the leaking bullhead valve was replaced and inspected. The pumper has noted that he will be sure to monitor and inspect the valves on a more frequent basis.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 120739

Corrective Action: Install sign to comply with Rule 210.d.

Date: 01/31/2019

Response: CA COMPLETED

Date of Completion: 12/29/2018

Operator
Comment:

the glycol bbl and white soap container were both removed 12/29/2018 therefore NFPA labels were not needed.
A NFPA sticker was placed on the green dehy pump tank and the capacity noted on tank as well. 12/29/2018

COGCC Decision:

COGCC
Representative:

3 CA# 120740

Corrective Action: Install sign to comply with Rule 210.b.

Date: 01/31/2019

Response: CA COMPLETED

Date of Completion: 12/29/2018

Operator
Comment:

The nearest CR "CR 25" was hand written on the wellhead sign until a new sign can be ordered and placed on location (spring).

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All deficiencies noted in the inspection have been addressed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Philana Thompson

Signed:

Title: Regulatory Compliance Spe

Date: 1/8/2019 8:45:33 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

--	--

Total Attach: 0 Files