

Inspection Photos
Location Name: Champlin Danford #44-32
Location ID: 320609



Photo 1 WH

Photo 2 TNK BTRY

Inspection Photos
Location Name: Champlin Danford #44-32
Location ID: 320609



Photo 3 Stained soil/trash PU

Photo 4 Gauge Hatch missing H2O tank