

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401896339
Date Received:
01/08/2019

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 56680
Name of Operator: MERRION OIL & GAS CORP
Address: 610 REILLY AVENUE
City: FARMINGTON State: NM Zip: 87401
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Thompson, Philana	(505) 486-1171	pthompson@merrion.bz

COGCC INSPECTION SUMMARY:

FIR Document Number: 679701950
Inspection Date: 11/30/2018 FIR Submit Date: 11/30/2018 FIR Status:

Inspected Operator Information:

Company Name: MERRION OIL & GAS CORP Company Number: 56680
Address: 610 REILLY AVENUE
City: FARMINGTON State: NM Zip: 87401

LOCATION - Location ID: 316123

Location Name: BAXTER PASS-64S103W Number: 21NESE County: RIO BLANCO
Qtrqr: NESE Sec: 21 Twp: 4S Range: 103W Meridian: 6
Latitude: 39.694710 Longitude: -108.955140

FACILITY - API Number: 05-103-00 Facility ID: 232180

Facility Name: BAXTER PASS Number: 43-21
Qtrqr: NESE Sec: 21 Twp: 4S Range: 103W Meridian: 6
Latitude: 39.694710 Longitude: -108.955140

CORRECTIVE ACTIONS:

1 ☒ CA# 120738

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 12/31/2018

Response: CA COMPLETED Date of Completion: 12/29/2018

Operator Comment: the leaking bullhead valve was replaced and inspected. The pumper has noted that he will be sure to monitor and inspect the valves on a more frequent basis.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 120739

Corrective Action: Install sign to comply with Rule 210.d.

Date: 01/31/2019

Response: CA COMPLETED

Date of Completion: 12/29/2018

Operator Comment: the glycol bbl and white soap container were both removed 12/29/2018 therefore NFPA labels were not needed.
A NFPA sticker was placed on the green dehy pump tank and the capacity noted on tank as well. 12/29/2018

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 120740

Corrective Action: Install sign to comply with Rule 210.b.

Date: 01/31/2019

Response: CA COMPLETED

Date of Completion: 12/29/2018

Operator Comment: The nearest CR "CR 25" was hand written on the wellhead sign until a new sign can be ordered and placed on location (spring).

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All deficiencies noted in the inspection have been addressed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Philana Thompson

Signed: _____

Title: Regulatory Compliance Spe

Date: 1/8/2019 8:45:33 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401896339	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files