

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/08/2019

Submitted Date:

01/09/2019

Document Number:

679300074**FIELD INSPECTION FORM**Loc ID 327218 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Evans, Jacob		jacob.evans@nblenergy.com	
Howard Aamold		Howard.Aamold@nblenergy.com	
Inspections, All		NBL_DJBU_Inspections@NB LENERGY.COM	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437656	TANK BATTERY	AC	04/14/2009		-	Spomer BC J 33-13,14	EI

**General Comment:**

COGCC Inspection in response to spill Document #401808067 reported by Operator. Excavation ongoing at the time of inspection. COGCC met with environmental personnel on site and was provided a remediation summary. Impacted soils appear to extend through vadose zone into the capillary fringe, groundwater and base soil sample results are pending.

**Location****Lease Road:**

Type	Access		
comment:	Access points have been added to accommodate remediation activities. Traffic control personnel in place, trucks staging off location to improve traffic flow. Minimal tracking on roads.		
Corrective ActionL		Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

**Good Housekeeping:**

Type			
Comment:	Overall site conditions good, stockpiles well managed.		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Environmental****Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)	
Oily Soil	Other	Adequate		
Comment	Impacted soil being hauled to Buffalo Ridge Landfill. Good traffic and tracking control.			
Corrective Action				Date:

**Spill/Remediation:**

Comment: Site requires a Form 27 for produced water vault removal. Operator will submit Supplemental Form 19 and Form 27 with excavation information upon completion of work.

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679300075	Excavation Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4698493">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4698493</a>