

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401898569

Date Received:

01/09/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10454  
Name of Operator: PETROSHARE CORPORATION  
Address: 9635 MAROON CIRCLE #400  
City: ENGLEWOOD State: CO Zip: 80112

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

| Contact Name   | Phone          | Email                      |
|----------------|----------------|----------------------------|
| Brown, Devin   | (303)-349-0302 | dbrown@petrosharecorp.com  |
| Pesicka, Conor |                | conor.pesicka@state.co.us  |
| Grimes, Meghan | (720) 441-0720 | mgrimes@petrosharecorp.com |
| Gomez, Jason   |                | jason.gomez@state.co.us    |

COGCC INSPECTION SUMMARY:

FIR Document Number: 688400987  
Inspection Date: 01/07/2019 FIR Submit Date: 01/07/2019 FIR Status:

Inspected Operator Information:

Company Name: PETROSHARE CORPORATION Company Number: 10454  
Address: 9635 MAROON CIRCLE #400  
City: ENGLEWOOD State: CO Zip: 80112

LOCATION - Location ID: 320190

Location Name: (UPRR) KALCEVIC-62S63W Number: 3SEW County: ADAMS  
Qtrqtr: SENW Sec: 3 Twp: 2S Range: 63W Meridian: 6  
Latitude: 39.906780 Longitude: -104.425600

FACILITY - API Number: 05-001-00 Facility ID: 202957

Facility Name: (UPRR) KALCEVIC Number: 22-3  
Qtrqtr: SENW Sec: 3 Twp: 2S Range: 63W Meridian: 6  
Latitude: 39.906780 Longitude: -104.425600

CORRECTIVE ACTIONS:

1 CA# 121541

Corrective Action: Comply with rule 1103 Date: 02/07/2019

Response: CA COMPLETED Date of Completion: 01/08/2019

Lines have been cut and capped underground.

Operator  
Comment:

COGCC Decision:

COGCC  
Representative:

**2** CA# 121542

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 01/08/2019

Response: CA COMPLETED

Date of Completion: 01/08/2019

Operator  
Comment:

Leaking load valve and load pot have been repaired. Photos attached.

COGCC Decision:

COGCC  
Representative:

**3** CA# 121543

Corrective Action: Install wildlife screen per Rule 605.b.(7).

Date: 02/07/2019

Response: CA COMPLETED

Date of Completion: 01/09/2019

Operator  
Comment:

Screen attached over separator stack.

COGCC Decision:

COGCC  
Representative:

**4** CA# 121544

Corrective Action: Install sign to comply with Rule 210.e.

Date: 02/07/2019

Response: CA COMPLETED

Date of Completion: 01/08/2019

Operator  
Comment:

New NFPA sign placed on production tank. Photo attached.

COGCC Decision:

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Devin Brown

Signed: \_\_\_\_\_

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <b><u>Document Number</u></b> | <b><u>Description</u></b>                     |
|-------------------------------|---|
| 401898596                     | failed load valve photo                       |
| 401898598                     | repaired load valve photos                    |
| 401898601                     | new NFPA tank sticker applied                 |
| 401898602                     | oily soil removed and backfilled at separator |

Total Attach: 4 Files