

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/03/2019

Submitted Date:

01/03/2019

Document Number:

689702346

FIELD INSPECTION FORM

Loc ID 335824 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
12 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------|-------|--|---------------------------|
| , Caerus Piceance | | COGCC.inspections@caerus oilandgas.com | Piceance inspections only |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 281919 | WELL | PR | 04/03/2007 | GW | 045-11570 | N.PARACHUTE EF08B C27A 595 | PR |
| 281923 | WELL | PR | 04/03/2007 | GW | 045-11575 | N. PARACHUTE EF09D C27A 595 | PR |
| 281924 | WELL | PR | 04/03/2007 | GW | 045-11576 | N.PARACHUTE EF 16B C27A 595 | PR |
| 281930 | WELL | PR | 04/03/2007 | GW | 045-11577 | N.PARACHUTE EF06B C27A 595 | PR |
| 281931 | WELL | PR | 04/03/2007 | GW | 045-11578 | N.PARACHUTE EF 10B C27A 595 | PR |
| 281933 | WELL | PR | 04/03/2007 | GW | 045-11579 | N.PARACHUTE EF 16D C27A 595 | PR |
| 281935 | WELL | PR | 04/03/2007 | GW | 045-11580 | N.PARACHUTE EF01B C27A 595 | PR |
| 281936 | WELL | PR | 04/03/2007 | GW | 045-11581 | N.PARACHUTE EF07B C27A 595 | PR |

General Comment:
Routine FIU General Field Inspection

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | No emergency services number or (911) on battery sign. Obstructed visibility of battery sign. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | Date: | 03/04/2019 |

| | | | |
|----------------------------------|--------------|-------|--|
| Emergency Contact Number: | | | |
| Comment: | 800-791-7691 | | |
| Corrective Action: | | Date: | |

Overall Good:

| Spills: | | | |
|----------------|------|--------|--|
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 281919 | Type: | WELL | API Number: | 045-11570 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 281923 | Type: | WELL | API Number: | 045-11575 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 281924 | Type: | WELL | API Number: | 045-11576 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 281930 | Type: | WELL | API Number: | 045-11577 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 281931 | Type: | WELL | API Number: | 045-11578 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 281933 | Type: | WELL | API Number: | 045-11579 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 281935 | Type: | WELL | API Number: | 045-11580 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 281936 | Type: | WELL | API Number: | 045-11581 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Compaction | Pass | | | | | |
| | | Compaction | | | | |
| | | | | Material Handling And Spill Prevention | | |
| | | Culverts | | | | |
| | | Ditches | | | | |
| Berms | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 401892702 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4694104 |
| 689702347 | Inspection 689702346 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4694100 |