

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/24/2018

Submitted Date:

01/03/2019

Document Number:

692400493**FIELD INSPECTION FORM**
 Loc ID 335867 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10091Name of Operator: BERRY PETROLEUM COMPANY LLCAddress: 5201 TRUXTUN AVENUE #100City: BAKERSFIELD State: CA Zip: 90339**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Johnson, Derek		DJohnson@bry.com	
Wilbourn, Don		dwilbourn@bry.com	
Armstrong, Jon		JArmstrong@bry.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288438	WELL	XX	02/26/2018	LO	045-13268	GRANLEE OM07B G03 696	RI

General Comment:

Location shows as Built in 2009 aeriels, and Not Built in 2006 (there is a two-year gap in aerial images). No wells were drilled or equipment installed on site; though excavated Pit area is visible in 2009 aeriels. APDs for Eight Wells were filed in 2006; Seven permits were Abandoned in 2018, leaving One XX Well, API#045-13268 Permit expiring 4/4/20 on Location. 2A was refiled in 2018, Approved with Expiration Date of 4/4/21. Surface Disturbance does appear to be at Eight acres as detailed in 2A. Steep Fill Slopes are rocky, with little to no vegetation. Approximately a dozen Concrete Jersey barriers are stored at West edge of Pad. Snow cover prevented a detailed assessment of pad Surface or access road conditions.

As Location was constructed and has not been Drilled or Reclaimed for ten years Operator will be required to go through the Notice to Operators: Interim Reclamation Procedures for Delayed Operations (January 5,2017). Refer to Reclamation Section.

Inspected Facilities									
Facility ID:	288438	Type:	WELL	API Number:	045-13268	Status:	XX	Insp. Status:	RI

--

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Excerpts from NTO Interim Reclamation Procedures for Delayed Operations:
Delayed operations may occur in the following scenario (3) an operator constructs a well location but does not drill any wells. Existing locations refer to locations constructed prior to January 3, 2017. Within six months of January 3, 2017 operators of existing locations will either commence interim reclamation or complete the variance request procedures described below.

Guidance may be found at COGCC Website:
Home > Regulation > Policies > Interim Reclamation Procedures for Delayed Operations-
Notice to Operators

Corrective Action

Submit an Interim Reclamation Variance Request for Location; reviewing Notice to Operators: Interim Reclamation Procedures for Delayed Operations January 5, 2017. Provide information as detailed in Part IV A.

Consult with Inspector if further clarification or guidance is needed.

Date **02/04/2019**

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: OTHER, RANGELAND _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

Inspector Name: Colby, Lou

TRANSECT RESULTS OF DISTURBED AREA% _____
TRANSECT RESULTS OF REFERENCE AREA% _____
TOTAL % OF DESIRABLE VEGETATION COVER _____
VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401892684	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4694083
692400494	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4694082