

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/10/2019

Submitted Date:

01/10/2019

Document Number:

689302934**FIELD INSPECTION FORM**
 Loc ID 334563 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc.inspections@caerusoila ndgas.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211184	WELL	TA	10/24/2014	GW	045-06943	PARKER RANCH 10-9	TA
259382	WELL	PR	10/17/2001	GW	045-07720	ROSE RANCH 10-16 (I10)	PR
259383	WELL	PR	08/30/2001	GW	045-07721	ANDREW 10-15 (I10)	PR
259384	WELL	PR	04/15/2002	GW	045-07722	ROSE RANCH 10-10 (I10)	PR
259385	WELL	SI	08/01/2018	GW	045-07723	ROSE RANCH 10-9A (I10)	SI

**General Comment:**

[Routine Field Inspection.](#)  
[Location is snow covered.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-791-7691

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 5	
Comment:		
Corrective Action:		Date:
Type: Pig Station	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:	2 tanks in a centralized battery.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 211184 Type: WELL API Number: 045-06943 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTEDComment: MIT current DOC# 401818140.Corrective Action: Date: Facility ID: 259382 Type: WELL API Number: 045-07720 Status: PR Insp. Status: PR**Producing Well**Comment: Well Producing on plunger lift.Corrective Action: Date: Facility ID: 259383 Type: WELL API Number: 045-07721 Status: PR Insp. Status: PR**Producing Well**Comment: Well Producing on plunger lift.Corrective Action: Date: Facility ID: 259384 Type: WELL API Number: 045-07722 Status: PR Insp. Status: PR**Producing Well**Comment: Well Producing on plunger lift.Corrective Action: Date: Facility ID: 259385 Type: WELL API Number: 045-07723 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: Well shut in at time of inspection.Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302935	Inspection photo 689302935	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4701193">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4701193</a>