

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/09/2019

Submitted Date:

01/11/2019

Document Number:

675001726**FIELD INSPECTION FORM**
 Loc ID 312609 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Reid, Jordan	(970) 563-4000	maralextechjr@gmail.com	All Inspections
Peicka, Conor		conor.pesicka@state.co.us	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Graves, Jim		mrinc20@qwestoffice.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222011	WELL	SI	05/01/2012	GW	077-08613	SOUTH SHALE RIDGE 7-24	SI

General Comment:

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable. This well is not part of Order 1V-609.

Date

Location			
Lease Road:			
Type	Access		
comment:	See stormwater section		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	No Wellhead sign		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 02/11/2019
Type	TANK LABELS/PLACARDS		
Comment:	Tank label is miss labeled. It says 300 bbls when it is only approximately 12' wide and approximately 10 feet tall at 1.67 barrels an inch this is a 200 barrel tank		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 03/11/2019
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-858-8550		
Corrective Action:			Date:
Good Housekeeping:			
Type			
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Vertical Separator	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	OTHER	Open Top		,
Comment:	See tanks labels under signs/markers				
Corrective Action:					Date: 03/11/2019

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	222011	Type:	WELL	API Number:	077-08613	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: Well last produced April 2010. MIT on 2/19/2015 Doc#400797603. Date									
Corrective Action: _____ Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: refer to inspection Access road to location has multiple areas of erosion across roadway and sediment migration down gradient of road surface. This location is a federal surface hence the inspection is being forwarded to a BLM representative so they may respond to the operator on what actions should be implemented. The road does not meet the da Access road to location has multiple areas of erosion across roadway and sediment migration down gradient of road surface. This location is a federal surface hence the inspection is being forwarded to a BLM representative so they may respond to the operator on what actions should be implemented. The road does not meet the COGCC stormwater rules for erosion and sediment migration. See attached photos.

Corrective Action: **Install or repair required BMPs per Rule 1002.f.**

Date: 08/07/2018

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675001741	Inspection 675001726 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4702113