

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
01/11/2019
Submitted Date:
01/11/2019
Document Number:
675001743

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Wentzel, Dougo On-Site Inspection
312606 _____ 2A Doc Num: _____

Operator Information:
OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED
Findings:
11 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
DNR		dnr_cogccengineering@state.co.us	All Enginnering
Peicka, Conor		conor.pesicka@state.co.us	All Inspections
Colby, Lou		lou.colby@state.co.us	
Murray, Richard		g.richard.murray@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amohare@maralexinc.com	All Inspections
Graves, Jim		mrinc20@qwestoffice.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222008	WELL	SI	05/01/2012	GW	077-08610	SOUTH SHALE RIDGE 9-17	PA

General Comment:

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.

Well plugged on 10/16/17. Form 6 (s) Doc#401654713 in process.
This is a top job on well. 40 sxs w/ KCI. WOC to tag. Tagged at 130'. 35 sxs w/ KCL. Did not get to surface. WOC. Tagged cement at 12'. Placed 6 sxs to bring to surface. No fall back.
Date

Location

Lease Road:			
Type	Access		
comment:	Winter conditions unplowes access road		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	No signage on location		
Corrective Action:	Unmarked riser left on location with hole in ground	Date:	02/11/2019

Emergency Contact Number:			
Comment:	See Signs and Markers		
Corrective Action:		Date:	_____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Riser left unmarked, untaged		
Corrective Action:	Comply with Rule 603.f .	Date:	01/11/2019

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 222008 Type: WELL API Number: 077-08610 Status: SI Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well plugged on 10/16/17. Form 6 (s) Doc#401654713 in process.
This is a top job on well. 40 sxs w/ KCl. WOC to tag. Tagged at 130'. 35 sxs w/ KCL. Did not get to surface. WOC. Tagged cement at 12'. Placed 6 sxs to bring to surface. No fall back. Refer to inspection 689401497 8/1/18

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675001744	Inspection 675001743 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4702116