

Inspection Photo (s)
Shideler 19-7B
API # 05-045-09452
Inspection # 689302942



Location Photo #1



Location Photo #2,

Inspection Photo (s)
Shideler 19-7B
API # 05-045-09452
Inspection # 689302942



Location Photo #3



**Location Photo #4, Holes in secondary liner,
near the stair access point.**

Inspection Photo (s)
Shideler 19-7B
API # 05-045-09452
Inspection # 689302942



Location Photo #5, Unmarked/unused flowline.



Location Photo #6, Unmarked/unused flowline.