

**Inspection Photo (s)**  
**ALP 25-16**  
**API # 05-045-09180**  
**Inspection # 689302952**



**Location Photo #1**



**Location Photo #2, Hole in secondary  
containment liner.**