

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/14/2019

Submitted Date:

01/14/2019

Document Number:

689302952**FIELD INSPECTION FORM**Loc ID 335321 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc.inspections@caerusoila ndgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266772	WELL	PR	10/09/2003	GW	045-09181	ALP 25-9C (J25)	PR
266773	WELL	PR	10/09/2003	GW	045-09180	ALP 25-16 (J25)	PR
266774	WELL	PR	11/01/2012	GW	045-09179	ALP 25-8C (J25)	PR
266796	WELL	PR	10/12/2003	GW	045-09184	ALP 25-10 (J25)	PR
266797	WELL	PR	06/11/2004	GW	045-09183	ALP 25-9 (J25)	PR
281899	WELL	PR	05/27/2006	GW	045-11567	ALP 25-9D(J25NW)	PR
281901	WELL	PR	05/27/2006	GW	045-11568	ALP 25-8CI (J25NW)	PR

General Comment:[Follow-up inspection from FIR DOC# 689302643 in response to FIRR DOC# 401883937 . Corrective actions have not been completed.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: 1-800-791-7691

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST		,	
Comment:		2 tanks in acentralized battery.				
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)	Methanol tank					
Other (Capacity)	1000 gallon					
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Inadequate		
Comment:		Hole in secndary liner near stair access, see photo.				
Corrective Action:		Repair or install berms or other secondary containment devices per Rule 906.d.(1).				Date: 01/14/2019
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	266772	Type:	WELL	API Number:	045-09181	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	266773	Type:	WELL	API Number:	045-09180	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	266774	Type:	WELL	API Number:	045-09179	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	266796	Type:	WELL	API Number:	045-09184	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	266797	Type:	WELL	API Number:	045-09183	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	281899	Type:	WELL	API Number:	045-11567	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	281901	Type:	WELL	API Number:	045-11568	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302953	Inspection photo 689302953	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4702731