

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/12/2019

Submitted Date:

01/12/2019

Document Number:

689302940

FIELD INSPECTION FORM

Loc ID 334886 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc.inspections@caerusoila ndgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211534	WELL	PR	06/01/2002	GW	045-07294	SHIDELER 19-8	PR
261628	WELL	PR	04/29/2003	GW	045-07968	SHIDELER 19-9B1 (H19)	PR
261629	WELL	PR	05/01/2003	GW	045-07969	SHIDELER 19-7DI (H19)	PR
264086	WELL	PR	04/14/2003	GW	045-08174	HMU 19-2D1 (H19)	PR
264087	WELL	PR	09/01/2018	GW	045-08175	HMU 19-3DI (H19)	PR
264088	WELL	PR	05/01/2003	GW	045-08176	HMU 19-1B1 (H19)	PR

General Comment:

This is a follow up inspection from [Doc# 689302587](#). Required Corrective Action (s) items noted in previous inspections have been satisfied.
Equipment inventory has not changed on location.

Inspected Facilities									
Facility ID:	211534	Type:	WELL	API Number:	045-07294	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing.								
Corrective Action:					Date:				
Facility ID:	261628	Type:	WELL	API Number:	045-07968	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	261629	Type:	WELL	API Number:	045-07969	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	264086	Type:	WELL	API Number:	045-08174	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	264087	Type:	WELL	API Number:	045-08175	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	264088	Type:	WELL	API Number:	045-08176	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302941	Inspection photo 689302941	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4702725