

**FORM  
INSP**Rev  
X/15

# State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/14/2019

Submitted Date:

01/14/2019

Document Number:

689302954

**FIELD INSPECTION FORM**
 Loc ID 334975 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc.inspections@caerusoila ndgas.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258805	WELL	PR	03/26/2004	GW	045-07660	DEVER 36-11	PR
258806	WELL	PR	06/01/2002	GW	045-07661	BENZEL 36-10 (K36)	PR
258807	WELL	PR	06/01/2002	GW	045-07662	DEVER 36-6 (K36)	PR
258808	WELL	PR	12/19/2000	GW	045-07663	DEVER 36-7 (K36)	PR

**General Comment:**

This is a follow up inspection from Doc# 689302647. Required Corrective Action (s) items noted in previous inspections have been satisfied.

Equipment inventory has not changed on location.

Inspected Facilities									
Facility ID:	258805	Type:	WELL	API Number:	045-07660	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	258806	Type:	WELL	API Number:	045-07661	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	258807	Type:	WELL	API Number:	045-07662	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	258808	Type:	WELL	API Number:	045-07663	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302955	Inspection photo 689302955	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4702732">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4702732</a>