

Inspection Photos
Location Name: Boies Ranch C-240 Pad
Location ID: #335678
Inspection Date: January 11, 2019



Photo #1 – View of facility sign and active drilling rig from the north.



Photo #2 – East bermed drill cuttings storage area. Operator indicated that surface cuttings had been moved from storage area to make room for additional production zone cuttings.

Inspection Photos

Location Name: Boies Ranch C-240 Pad

Location ID: #335678

Inspection Date: January 11, 2019



Photo #3 – West bermed drill cuttings area (view from NE) had production zone cuttings on inspection date. Note fluids accumulation on top of cuttings (red arrow).



Photo #4 – West bermed drill cuttings area (view from NW)



Inspection Photos
Location Name: Boies Ranch C-240 Pad
Location ID: #335678
Inspection Date: January 11, 2019



Photo #5 – View of drilling rig and cuttings shaker from south.



Photo #6 – Western produced water tank had damaged insulation on inspection date.