

Inspection Photos
Operator Name: Caerus Piceance LLC
Location ID: 312691



Sink hole looking west



Sink hole looking east

Inspection Photos
Operator Name: Caerus Piceance LLC
Location ID: 312691



Holes in pipe, 2nd hole under vac truck hose. Looking east



1st hole on west side

Inspection Photos
Operator Name: Caerus Piceance LLC
Location ID: 312691



Repairs made to Flowline, Looking west



Repairs made to Flowline, Looking west