

Interim Reclamation and Stormwater Inspection

January 8, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP – 47120

Location ID: 451781

Inspection Document #: 674902406

Weld County, CO

SESE Section 17 T1N R66W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP - 47120/1N66W17

Location ID: 451781



Photo 1. Photo taken from the location, facing East. Appears the Operator has started interim reclamation activities to reduce disturbance areas only needed for production operations at the location. However, no evidence of drilling rows and straw crimped mulch were observed.

Photo 2. Photo taken from the location, facing North. See comments from Photo 1.

Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP - 47120/1N66W17

Location ID: 451781



Photo 3. Photo taken from the location, facing East. See comments from Photo 1.



Photo 4. Photo taken from the location, facing South. See comments from Photo 1.

Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP - 47120/1N66W17

Location ID: 451781



Photo 5. Photo taken from the location, facing East. See comments from Photo 1.



Photo 6. Photo taken from the location, facing West. See comments from Photo 1.

Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP - 47120/1N66W17

Location ID: 451781



Photo 7. Photo taken from the location, facing North.
See comments from Photo 1.



Photo 8. Photo taken from the access road, facing West.
See comments from Photo 1.