

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/14/2019

Submitted Date:

01/14/2019

Document Number:

690002993

FIELD INSPECTION FORM

Loc ID 306713 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290601	WELL	PR	08/01/2018	OW	123-25149	CIZEK-USX T 1-8	PR

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type TANK BATTERY

Comment: Barb Wire

Corrective Action:

Date:

Type WELLHEAD

Comment: Pipe

Corrective Action:

Date:

Type SEPARATOR

Comment: Barb Wire

Corrective Action:

Date:

Type IGNITOR/COMBUSTOR

Comment: Barb Wire

Corrective Action:

Date:

Equipment:

corrective date

Type: Gas Meter Run # 1

Comment:

Corrective Action:

Date:

Type: Emission Control Device # 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date:

Type: Bird Protectors # 2

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator # 1

Comment:

Corrective Action:	Date:
--------------------	-------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER			

Comment:	Date:
Corrective Action:	Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	60 Bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shared with crude oil tank.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.259030,-104.943010

Comment:	Date:
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	Ignitor/Combustor
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 290601 Type: WELL API Number: 123-25149 Status: PR Insp. Status: PR

Producing Well

Comment: [PR](#)

Corrective Action:

Date:

BradenHead

Comment: [Bradenhead plumbed to the surface.](#)

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Routine inspection.	carlilec	01/14/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690002994	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4703126