

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/29/2018

Submitted Date:

01/14/2019

Document Number:

692400575**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 398147      Colby, Lou      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 22315Name of Operator: D & D RESOURCES, INCAddress: 2835 VILLA WAY #4City: GRAND JUNCTION      State: CO      Zip: 81501**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	
Conklin, Curtis		curtis.conklin@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231219	WELL	PA	01/14/1999	OW	103-08888	EMERALD 246	RI

**General Comment:**

This is a Follow Up to Insp Doc#680102200 dated 8/31/17; conducted to verify status of site conditions & to recommend this Location to the Orphaned Well Program; at the least to facilitate having the Open tank hatch closed. Since prior attempts in 2017 to contact Operator, it has been determined that Mr. Burl Dailey (Operator D&D Resources) is deceased. Below are General Comments from previous Inspection attempting to explain this confusing site. Conditions at site have not changed since previous Inspections.

"This is a Reclamation Inspection; Bond Release Related & a Follow Up to Insp#675102462 dated 4/28/2016 for Well API#103-08888. Any Corrective Actions from previous Inspections that have not been addressed are still applicable. Well was Spud 11/12/1982 by Diamond Back Drilling. Well appears TA(Temporarily Abandoned) not P&A (Plugged & Abandoned), though Scout Card and Documents on File report P&A 1/14/1999 by Equity Oil. Aerials & coordinates all match up to identify this TA Well as API#103-08888. It is likely that the Well was confused with numerous adjacent P&A'd Emerald Wells in Historical Inspections and Passed in Error. Operator has not responded to Previous Field Inspection Corrective Actions; among them 24 hour notice to close gauge hatches by 4/29/16; other CA Dates of 6/3/2016 & 7/4/16 have not been met. Previous Insp is attached to this Insp & print copy will be sent to Operator.

Inspection will be referred to area Engineer as TA status of this Well show it delinquent for MIT .

Operator has no email contact address in system. Inspections will be mailed via USPS to physical address on File: D & D Resources C/O BURL DAILEY 2835 VILLA WAY #4 ,GRAND JUNCTION, CO 81501. Inspection will be mailed out Tuesday. September 9, 2017."



**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? **Fail** \_\_\_\_\_Comment Debris remains on Location.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? **Fail** \_\_\_\_\_Comment Unused, unneeded equipment remains on Location.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? Fail Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

## 1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment Interim Reclamation areas do not currently meet the 80% of Reference area requirement.  
Refer to Photos attached for detail of Site Conditions.

Corrective Action  Date \_\_\_\_\_

Overall Interim Reclamation Fail

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:  Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [There appear to be no Stormwater controls / BMPs installed at this site. There is also no secondary containment installed for equipment.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692400576	Field Inspection 4/28/17	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4703766">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4703766</a>
692400577	Photos 4/28/17	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4703767">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4703767</a>
692400578	Photos 8/31/17	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4703768">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4703768</a>