

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/14/2019

Submitted Date:

01/14/2019

Document Number:

694400077**FIELD INSPECTION FORM**
 Loc ID 456260 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		COGCCInspections@extracti onog.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456260	LOCATION	AC			-	MERLIN PAD	AC

General Comment:

Inspected Facilities

Facility ID: 456260 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Complaint

Comment: [Inspection in response to complaint.](#)

Field Inspector Assigned: Adam Kraich

Complaint Received:

Date: 1/14/2019

Complaint Contacted:

Date: 1/14/2019 @ 14:28

Location #: 456260

Inspection Document #: 694400077

Nature of complaint: Noise, Odor, Lighting.

Field Inspector Actions:

On 01-14-2019, I received a complaint in regard to noise, odors, and lighting coming from the Merlin Pad, owned and operated by Extraction Oil & Gas.

On 1-14-2019, I performed an inspection of the location.

Noise: I performed a sound audit 350' southeast of the location sound walls (40.45696, -104.92569). The audit revealed an average of 56.8 DB (A). Compliance under rule 802.

Odor: Extraction appears to be utilizing petroleum based drilling fluid. Using CDPHE regulation 2 method, I identified no odors off location at time of inspection.

Lighting: During inspection, I observed all rig lighting to be pointed inward and downward. Compliance under 803.

No violation of COGCC rules were observed at the time of the inspection.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action:

Date:

Well Drilling

Rig: Rig Name: Patterson 901 Pusher/Rig Manager: Manny
Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
Multi-Well: _____ Disposal Location: _____

Comment: [Inspection in response to local complaint.](#)

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694400078	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4703873
694400079	Sound Audit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4703874