

Interim Reclamation and Stormwater Inspection

January 9, 2019

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 453242

Inspection Document #: 682404414

Weld County, CO

SENE Section 34 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Mustang /42-34
Location ID: 453242



Photo 1. Photo taken from the entrance of the location, facing West. Photo illustrates Operator sign. Another Operator sign was located next to the pumpjack. Appears the Operator has performed interim reclamation activities to reduce disturbance areas only needed for production operations.




Photo 2. Photo taken from the entrance of the location, facing North. Operator has performed interim reclamation activities with the evidence of drilling rows and straw crimped mulch. Interim areas appear to be properly contoured to the surrounding landscape.

Inspection Photos
Location Name: Mustang /42-34
Location ID: 453242



Photo 3. Photo taken from the northeastern interim reclamation area, facing West. See comments under Photo 2.



Photo 4. Close up photo taken from the northern interim reclamation area. Some germination was observed throughout portions of the interim area.

Inspection Photos
Location Name: Mustang /42-34
Location ID: 453242



Photo 5. Photo taken from the northern production area, facing West. All locations shall be kept free of supplies not necessary for use on that lease per Rule 603.f.



Photo 6. Photo taken from the western production area, facing Southwest. See comments under Photo 5.

Inspection Photos
Location Name: Mustang /42-34
Location ID: 453242



Photo 7. Photo taken from the western production area, facing South. See comments under Photo 1.



Photo 8. Photo taken from the southwestern production area, facing South. See comments under Photo 1.

Inspection Photos
Location Name: Mustang /42-34
Location ID: 453242



Photo 9. Photo taken from the southwestern perimeter of the location, facing West. Appears to be a relic ditch BMP that needs to be stabilized, as this is unconsolidated material that is susceptible to wind and water erosion. Wind erosion soil particle deposition was observed off Location at other nearby locations.



Photo 10. Photo taken from the southwestern perimeter of the location, facing East. See comments under Photo 9.

Inspection Photos
Location Name: Mustang /42-34
Location ID: 453242



Photo 11. Photo taken from the southwestern perimeter of the location, facing North. See comments under Photo 9.



Photo 12. Photo taken from the southern cut slope of the location, facing East. See comments under Photo 9.

Inspection Photos
Location Name: Mustang /42-34
Location ID: 453242



Photo 13. Photo taken from the southeastern interim reclamation area, facing East. See comments under Photo 2.



Photo 14. Photo taken from the southern production area, facing West. See comments under Photo 5.