

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/15/2019

Submitted Date:

01/15/2019

Document Number:

679702596**FIELD INSPECTION FORM**

Loc ID 336555 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name    | Phone        | Email                      | Comment |
|-----------------|--------------|----------------------------|---------|
| Waldron, Emily  |              | emily.waldron@state.co.us  |         |
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us |         |
| Peterson, Diane | 970-675-3842 | dlpe@chevron.com           |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 270963      | WELL | PR     | 04/01/2017  | OW         | 103-10414 | MC HAGOOD A 10X | PR          |
| 270964      | WELL | PR     | 02/01/2012  | OW         | 103-10413 | MC HAGOOD A 11X | PR          |

**General Comment:**

routine well inspection

**Location**Overall Good: ☒

|                      |            |       |  |
|----------------------|------------|-------|--|
| <b>Signs/Marker:</b> |            |       |  |
| Type                 | OTHER      |       |  |
| Comment:             | lease road |       |  |
| Corrective Action:   |            | Date: |  |
| Type                 | WELLHEAD   |       |  |
| Comment:             |            |       |  |
| Corrective Action:   |            | Date: |  |
| Type                 | CONTAINERS |       |  |
| Comment:             |            |       |  |
| Corrective Action:   |            | Date: |  |

Emergency Contact Number:

Comment: 970-675-3700

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                           |   |       |                 |
|---------------------------|---|-------|-----------------|
| <b>Equipment:</b>         |   |       | corrective date |
| Type: Submersible Pump    | # 1   |       |                 |
| Comment:                  |   |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Deadman # & Marked  | # 4   |       |                 |
| Comment:                  |   |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Ancillary equipment | # 1   |       |                 |
| Comment:                  | container of corrosion inhibitor with secondary containment |       |                 |
| Corrective Action:        |   | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 270963 Type: WELL API Number: 103-10414 Status: PR Insp. Status: PR**Producing Well**Comment: producing well on subpump

Corrective Action:

Date:

Facility ID: 270964 Type: WELL API Number: 103-10413 Status: PR Insp. Status: PR**Producing Well**Comment: producing well on subpump

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            |                 |                         |                       |               |                          |         |
| Compaction       |                 | Compaction              |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description      | URL   |
|--------------|------------------|---|
| 679702597    | inspection photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4704984">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4704984</a> |