

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/15/2019

Submitted Date:

01/15/2019

Document Number:

679702600

**FIELD INSPECTION FORM**

Loc ID 336557 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 16700  
Name of Operator: CHEVRON USA INC  
Address: 6301 DEAUVILLE BLVD  
City: MIDLAND State: TX Zip: 79706

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name    | Phone        | Email                      | Comment |
|-----------------|--------------|----------------------------|---------|
| Waldron, Emily  |              | emily.waldron@state.co.us  |         |
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us |         |
| Peterson, Diane | 970-675-3842 | dlpe@chevron.com           |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 279654      | WELL | PR     | 01/01/2018  | OW         | 103-10628 | M.C. HAGOOD A 15X | PR          |
| 279655      | WELL | SI     | 04/01/2018  | OW         | 103-10629 | M.C.HAGOOD A 17X  | SI          |

**General Comment:**

routine well inspection

**Location**

Overall Good:

**Signs/Marker:**

|                    |            |       |  |
|--------------------|------------|-------|--|
| Type               | CONTAINERS |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |
| Type               | OTHER      |       |  |
| Comment:           | lease road |       |  |
| Corrective Action: |            | Date: |  |
| Type               | WELLHEAD   |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |

Emergency Contact Number:

Comment: 970-675-3700

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type                |   |       | corrective date |
|---------------------|---|-------|-----------------|
| Ancillary equipment | # 1   |       |                 |
| Comment:            | container of corrosion inhibitor with secondary containment |       |                 |
| Corrective Action:  |   | Date: |                 |
| Deadman # & Marked  | # 4   |       |                 |
| Comment:            |   |       |                 |
| Corrective Action:  |   | Date: |                 |
| Submersible Pump    | # 2   |       |                 |
| Comment:            |   |       |                 |
| Corrective Action:  |   | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 279654 Type: WELL API Number: 103-10628 Status: PR Insp. Status: PR

**Producing Well**

Comment: [producing well on subpump](#)

Corrective Action:

Date:

Facility ID: 279655 Type: WELL API Number: 103-10629 Status: SI Insp. Status: SI

**Producing Well**

Comment: [Last reported production April 2018.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       |                 | Compaction              |                       |               |                          |         |
| Berms            |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description      | URL   |
|--------------|------------------|---|
| 679702601    | inspection photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4704986">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4704986</a> |