

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/16/2019

Submitted Date:

01/16/2019

Document Number:

688401047

**FIELD INSPECTION FORM**

Loc ID 333924 Inspector Name: Silver, Randy On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 1001 17TH STREET #1000  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 10 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us	All Inspections
Amato, Joseph	719-845-2110/719-859-2263	josephamato@tcenergy.us	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258755	WELL	PR	01/24/2007	GW	071-07144	HILL RANCH 03-02V	PR
258964	WELL	PR	05/23/2007	GW	071-07173	HILL RANCH 03-02R	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER				
Comment:	Location sign				
Corrective Action:				Date:	

**Emergency Contact Number:**

Comment:					
Corrective Action:				Date:	

**Good Housekeeping:**

Type	OTHER				
Comment:	stained soil around motor skid caused by fluid spilling out of skid				
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e			Date:	02/16/2019
Type					
Comment:	Fluid in motor skid is full and spilling over onto ground.				
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A			Date:	01/18/2019

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type					
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO				
Comment:					
Corrective Action:				Date:	

**Flaring:**

Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 258755 Type: WELL API Number: 071-07144 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Comment: Apears not to be plumbed to surface

Corrective Action:

Date:

Facility ID: 258964 Type: WELL API Number: 071-07173 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Comment: Apears not to be plumbed to surface

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
This is a follow up inspection per DOC #687903283. At time of inspection could not determine is pit had been drained due to snow. Unused equipment appears to be removed. At time of inspection Contacted Timber Creek rep and informed them about fluid spilling out of motor skid on the Hill Ranch #03-02R well.	silverr	01/16/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401048	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4706163">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4706163</a>