

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/17/2019

Submitted Date:

01/17/2019

Document Number:

689302988

FIELD INSPECTION FORM

Loc ID 334631 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Rider, Lindsay	970-285-2711	cogcc.inspections@caerusoila ndgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273995	WELL	PR	05/22/2009	GW	045-10309	HMU 16-2 (B16W)	PR
276639	WELL	PR	12/25/2008	GW	045-10500	HMU 9-15C (B16W)	PR
276643	WELL	PR	01/01/2009	GW	045-10501	HMU 16-2C (B16W)	PR
276644	WELL	PR	01/05/2009	GW	045-10502	HMU 16-7(B16W)	PR
276645	WELL	PR	01/10/2009	GW	045-10503	HMU 16-6 (B16W)	PR
295826	WELL	PR	12/25/2008	GW	045-15819	ROSE RANCH 16-1C (B16W)	PR

General Comment:

[Routine Field Inspection.](#)

Location

Lease Road:			
Type	Access		
comment:	snow packed.		
Corrective Action			Date:

Overall Good:

Emergency Contact Number:			
Comment:	1-800-791-7691		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:			Date:
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	OTHER	STEEL AST		,
Comment:	250 bbls tanks, 2 tanks are heated.				

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate		
Other (Content)	Methanol tank		
Other (Capacity)	24 bbls		
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	<u>273995</u>	Type:	<u>WELL</u>	API Number:	<u>045-10309</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:					Date:				
Facility ID:	<u>276639</u>	Type:	<u>WELL</u>	API Number:	<u>045-10500</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:					Date:				
Facility ID:	<u>276643</u>	Type:	<u>WELL</u>	API Number:	<u>045-10501</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:					Date:				
Facility ID:	<u>276644</u>	Type:	<u>WELL</u>	API Number:	<u>045-10502</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:					Date:				
Facility ID:	<u>276645</u>	Type:	<u>WELL</u>	API Number:	<u>045-10503</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:					Date:				
Facility ID:	<u>295826</u>	Type:	<u>WELL</u>	API Number:	<u>045-15819</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302989	Inspection photo 689302989	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4706602