

Inspection Photos
Location Name: Hwy. 151 34-4-30 MW #1
API: 05-067-06271



Hwy. 151 monitoring well location photo.



Monitoring well #1 bled down with a puff.

Inspection Photos
Location Name: Hwy. 151 34-4-30 MW #1
API: 05-067-06271



Removing rugged cable from well bore.



Water level measured at 43.10' from top of casing with 1.45' stick up from top of collar.

Inspection Photos
Location Name: Hwy. 151 34-4-30 MW #1
API: 05-067-06271



New Level Troll 700 series 1000 psia pressure transducer installed with 285' new rugged cable in monitoring well #1.



New Level Troll 700 series 1000 psia pressure transducer installed in upper position in monitoring well #1.

Inspection Photos
Location Name: Hwy. 151 34-4-30 MW #1
API: 05-067-06271



Monitoring well #1 after equipment replacements.



Desiccants replaced in July of 2018 appear fresh.